Upgrading the firmware



- 3. In the **Service Tree**, navigate to **Scripts > Scripts**.
- 4. Run the following script: Kodak\Proofer Client\ JavaScripts\ MachineControl\ update dsp firmware.js.
- 5. When prompted whether to auto-detect the DSP device type, click **Yes**.

The firmware upgrade takes about two minutes per device.

- 1. In the Scripting view, look at the Output pane to confirm that each DSP successfully upgraded.
- If the upgrade is successful, disconnect the USB cable from the Proofer Controller, wait two seconds, and then reconnect it. Exit the Service window.
- If the upgrade was unsuccessful, contact a service representative.