

Troubleshooting the Ink Optimizing Solution

Problem	Solution
My presswork with Ink Optimizing Solution doesn't look like it did before.	<p>Do any the following:</p> <ul style="list-style-type: none">• Ensure that the current press condition matches the initial characterization used to create the ink-optimizing DeviceLink. To accomplish this in ColorFlow, generate a Print Characterization report and compare it to current readings from the press run• Check for common press issues (black unit issues)• Confirm that the proofing setup matches the press• Run Prinergy Virtual Proofing System (VPS) separations as an acceptance procedure to verify that the ink-optimizing DeviceLink did not change the color
I cannot change the color on-press for an Ink Optimizing Solution job.	Decrease the Black Strength at the expense of press stability and ink savings