

Troubleshooting the Ink Optimizing Solution

Problem	Solution
My presswork with Ink Optimizing Solution doesn't look like it did before.	Do any the following: • Ensure that the current press condition matches the initial characterization used to create the ink-optimizing DeviceLink. To accomplish this in ColorFlow, generate a Print Characterization report and compare it to current readings from the press run • Check for common press issues (black unit issues) • Confirm that the proofing setup matches the press • Run Prinergy Virtual Proofing System (VPS) separations as an acceptance procedure to verify that the ink-optimizing DeviceLink did not change the color
I cannot change the color on-press for an Ink Optimizing Solution job.	Decrease the Black Strength at the expense of press stability and ink savings