_define Mindot

Define the **Process Inks (CMYK)** and **Spot Inks** Mindot:

- To use bump curves, enter 0.39 in the **Tint In** box and enter minimum printable dot value in the **Minimum Tint Out** box.
- To use cutoff curves, enter the minimum printable dot value in both the **Tint In** and **Minimum Tint Out** boxes.