Device section of the Publish File process template 1

Output Blank Surfaces for Duplexing and Collating

Select this check box when you want to output an imposition that is supposed to have blank surfaces (that is, surfaces with no separations) so that duplexing or collating will be correct.