

Calibrating color monitors

Before you can view color-accurate surfaces, your color monitor or monitors must be successfully calibrated. Monitor calibration must be done to ensure accurate color viewing.

When calibration finishes successfully, **Status: Calibrated** appears at the bottom of the left pane when you view a surface in Window mode. The date and time at which the calibration expires is also listed.

For more information, see the *Calibrating the color monitors* section in the *PressProof Quick Start Guide*.