

Leave the monitor turned on at all times

Do not turn off the monitor during use. You can allow a screen saver to turn on; this does not affect calibration.

If the monitor is accidentally turned off, turn it on, leave it on for at least 10 minutes, and then try again to calibrate the monitor. The MV calibration tool checks for stability. If a sufficient warm-up time has not been achieved, calibration will not be successful.