

Activating a measurement data set

You can establish a new color response for a device condition based on [measurement data](#) that you previously collected for the device condition.

1. In a device condition in the viewer window, click the Measurements icon  next to a device.
2. In the **Measurements** dialog box, click the **Measurements** tab.
3. Expand the **Inactive Measurements** section, and select a measurement data set.
4. Click **Activate**.

A color response is calculated from the measurement data set that you selected, and replaces the previous color response of this device condition.