

Exporting device curves

1. Click the device in a device condition, and then click **Export > Device Curves**.
2. In the **Save Curves** dialog box, browse to the location where you want to save the curve.
3. Use the default file name for the curve or type a new file name, and click **Save**. The curve is saved in Harmony format, as a .hmy file.