

Generating a Print Characterization report

You can create a Print Characterization report in PDF format to see detailed information about the state of a device in a device condition.

1. In a device condition in the color setup viewer, next to the device name, click the **Measurements** icon .
2. Click the **Measurements** tab.
3. In the **Active Measurement** area, select a measurement set or an individual sheet.
4. Click **Report**.
5. Do the following:
 - If you want to hide the explanatory text in the report, clear the **Include explanatory text** check box
 - In the **Customer** box, enter the report name. It will appear on the cover of the report
 - In the **Subtitle** box, enter additional information about the report. It will appear on the front cover and the footer of every page
 - In the **Inks** box, enter the ink product name or type used to print the chart
 - In the **Notes** box, enter the note if required
6. From the **Process Ink Sequence** list, select the ink sequence in the press when the chart was printed. Process ink sequence affects computation of Apparent Traps.
7. Clear the **Compare to** check box if it's selected.
8. Click **Save** and browse to the location where you want to save the report file.