

_highlight contrast control

To adjust the transition from the Mindot to the defined curve, adjust the **Highlight Contrast** slider or enter a value in the box. For most cases, the default value of 70% is acceptable.

- Reducing Highlight Contrast produces a curve that is flatter near the Mindot, meeting the defined curve at a lower point but reducing contrast in this region.
- Increasing Highlight Contrast produces a curve that preserves highlight contrast, but meets the defined curve at a higher point.