

Committing transfer curve adjustments

When you commit adjustments for a transfer curve, the curve channels do not change. The display of curve adjustments resets to zero, establishing a new baseline for curve adjustments.

1. In the **Print Curves** tab, find and click the print transfer curve whose adjustments you want to commit.
2. Click **Adjust**.
3. If desired, click **Transfer Curves** to view the curve shapes.
4. Click **Commit**.