

Applying calibration curves

1. Make sure Harmony software is installed.
See the Prinergy Evo Installation Guide for more information.
2. With the Harmony software, create calibration curves on the attached device.
See the Harmony User Guide for more information about working with Harmony software.
3. [Creating process templates](#).
4. In the **Calibration & Screening** section, **Harmony** list, select the optimum calibration curve.
Prinergy Evo reads the list of calibration curves from the Harmony database installed on the Prinergy Evo server computer.