

Printing proofs for Color Confirmation

Submit jobs to the workflow processing setup that you configured for the Certified Process for Color Confirmation.

Requirements:

- The color bar and workflow processing setup must be configured for the Certified Process for Color Confirmation.
- Kodak Proofing Software must have a current calibration for the media configuration.

The software uses the setup to print the color of the proof within your desired tolerances.

1. Submit the job files to the workflow processing setup.
The workflow software uses the profile to color-manage the color bar and job, the proofer prints the proof, and the spectrophotometer confirms that the color is within the specified tolerances.
Note: When Kodak Proofing Software receives the job, it checks that it meets the Certified Process for Color Confirmation requirements. If any components are missing, the job fails.
2. (Optional) Review the measurement results on the printed label and in the optional Color Confirmation report.