

# Exceptions to automatic extraction of the bleed path

Pandora extracts the shape of the bleed path by analyzing the cut lines in the die station. Failure to extract a bleed path can be caused by:

- Gaps in the cut outline
- A cut line that protrudes from the die station. If the die needs cut lines between the die stations, define the cut lines as top-level elements (that is, not part of the block that defines the die station).
- No cut lines specified in the die
- All lines in the die being specified as cut lines (this circumstance results in a malformed bleed path)