


Exporting measurement data

You can export a measurement data set from ColorFlow.

1. In a device condition in the viewer window, click the Measurements icon  next to a device.
2. In the **Measurements** dialog box, click the **Measurements** tab.
3. In the **Active Measurement** area, select a measurement data set.
4. Click **Export**.
5. Browse to the location where you want to save the measurement data set, and click **Save**.

The measurement data set is saved as a .cgt file, in CGATS.5 format. If you have measured multiple sheets, the exported file contains the average of all sheets.