

Exporting resources

You may find it convenient to set up a **ShopMap** palette in one installation of the Pandora software with some or all of the equipment or materials you plan to use, and export each equipment or material resource from the **ShopMap** palette as an XML file.

Note: You cannot export an output device profile separately because it is part of the device configuration.

1. If the **ShopMap** palette is not currently shown, select **Window > Show ShopMap Palette**.
2. Click **Materials** or **Equipment**, depending on the resource you want to export.
3. Click the tab that includes the type of resource you want to export.
4. In the list on the tab, select the resource you want to export.
5. Click the **options** arrow on the **ShopMap** palette, and then select **Export**.
6. In the Export dialog box, browse to the folder where you want to place the XML file you are exporting.
7. In the **Name** box, type a name for the XML file you are creating, and then click **Save**.