Setting required exclusions in Windows Defender

This procedure is only required for systems deployed with an OS prior to Win 10 IoT (LTSB /LTSC).


Before you can set the required proofing folder exclusions in Defender, the folders need to be installed by the proofing software installer. You can then proceed to configure exclusions for files and folders that require read and write access.

Note: If you prefer a third-party antivirus solution, continue configuring Defender exclusions and allow the third-party tool to provide protection until you finish setting up the proofing system. After that, it is your responsibility to set up the software you are using to replace Defender. You may find Partner Place Answer 43544 helpful (requires Partner Place login). The information in this answer uses McAfee software as an example of recommended settings. The excluded file types require read and write access, and the excluded file locations must include subfolders.

1. In the search box, type windows defender security center and then select it from the list of matches.




2. Click Virus & threat protection.




3. Click Virus & threat protection settings.



4. Scroll to Exclusions and click Add or remove exclusions.



5. Click **Add an exclusion** to display the following list:



File

Folder

File type

Process

6. Repeat for each of the following paths: click **Folder**, locate and select the folder, and click **Select Folder**:

Note: If RSS is not installed, the $C:\Program\ Files\ (x86)\Kodak\ folder\ will not\ be included in the list. If this is the case, create the folder and then exclude it.$

- C:\Creo
- C:\Program Files (x86)\Kodak
- C:\Program Files (x86)\MATLAB
- C:\Program Files (x86)\TightVNC
- D:\Program Files\Kodak
- 7. Repeat for each of the following file name extensions: click **File type**, type the characters, and click **Add**.
 - CAB
 - creotif
 - install
 - JAR
 - PDF
 - TIF
 - XML
 - 7.TP
- **8.** Repeat for each of the following processes: click **Process**, type the process name, and click **Add**.
 - Bonjour Service (might already be excluded)
 - ProoferService.exe
 - ColorEngineDaemon.exe
 - ControllerDaemon.exe
 - CRCColorEngine.exe
 - CreoServicePort.exe
 - CXAdminD
 - CXDiagLogD.exe
 - CXProoferD
 - CXReportEngineD.exe
 - eEBAPI

Folder
Kodak Folder
MATLAB Folder
Kodak Folder
CAB File type
creotif File type
install File type
JAR File type
PDF File type
TIF File type
XML File type
ZIP File type
Bonjour Service Process
ColorEngineDaemon.exe Process
ControllerDaemon.exe Process
CRCColorEngine.exe Process
CreoServicePort.exe Process
CXAdminD Process
CXDiagLogD.exe Process
CXProoferD Process
CXReportEngineD.exe Process
eEBAPI Process
ProoferService.exe Process

+ Add an exclusion

9. When the exclusion lists look like the following example, close all open windows.