

Creating a CF2 file by step-and-repeating an EPS file

CAD Correct can import an EPS file of the die-line separation, identify the die lines, step the file to create the die layout, and produce a CF2 file for Pandora software.

To step and repeat a file:

1. Open the file in CAD Correct.
For more information about opening files, see [Opening Files](#).
If the lines do not display as **Cut** in the **Show Line Type** list, change all lines to cut lines.
2. Create a step and repeat.
For information about creating a step and repeat, see [Stepping and repeating items](#).
3. Save a CF2 file for use in Pandora software.
For information about saving files, see [Saving a file](#).