

Knockout marks

Knockout marks appear white, and are only visible when you place them over artwork or another mark.

Knockout mark	Description
KO_Corner_Radii_0.125-inch.pdf	Removes image between die stations, creating white space that can be used for registration and calibration marks
KO_Corner_Radii_0.25-inch.pdf	Removes image between die stations, creating white space that can be used for registration and calibration marks. This larger mark is useful for printing credit card type products.
KO_Glue_Strip.pdf	Knocks out a space for a thin bead of glue