

Spectrophotometers, as needed

At any workstation that will be used to measure colors, you require a spectrophotometer and the applicable driver software. For information about supported spectrophotometers for your proofer type, see the applicable topics.

Important

- If adding or upgrading a supported spectrophotometer, ensure that it uses the latest device firmware available from the manufacturer.
- Kodak strongly recommends regular factory service and re-certification of spectrophotometers. See detailed information under [Importance of regular calibration and maintenance for spectrophotometers](#).